


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

SEE GRANT
RECORD SURV
NO 109a

INDEX No. C-8

History of original corner establishment:

None. Corner was established as part of this survey.



Description of corner evidence found:

None.

Description of monument and accessories | established to perpetuate the original location of this corner:

At position determined by survey... Set a 2½" x 30" aluminum pipe with standard ¾" USDA aluminum cap 24" in ground and surrounded with mound of earth & stone. Cap marked as shown in corner diagram.

New bearing trees established:


A 14" ponderosa pine brs S67½°W, 30.6' scribed C-E 1/16 S5 BT.

A 7" ponderosa pine brs S81½°W, 3.8' scribed C-E 1/16 S5 BT.

New bearing trees have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9 to each BT & painted face of blaze & 6" red band around each BT. Set steel fence posts on National Forest Boundary S & W of corner and attached sign 54-2 to both posts and 54-9 to one post.

Compass declination 18° East.

I hereby certify that the above corner was properly established by me to U.S.F.S. standards and witnessed by Bill Quaempts on July 13, 1989.



Office of.....County Surveyor.....County of.....Grant.....
 State of.....Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the 29 day of Mar, 1990
Robert D. Rogers by
 (COUNTY OFFICIAL) (DEPUTY)