


CERTIFIED RECORD OF LAND CORNER MONUMENTATION SURVEY NO 1094

SEE RECORD

Index No. E - 8

History of original corner establishment:

None. Corner established as part of this survey.



Description of corner evidence found:

Old location poster on corner tree.

Description of monument and accessories | established to perpetuate the original location of this corner:

The corner point falls on the East side of tree 0.4' East of centerline of tree. Therefore the 12" douglas fir was marked as the corner tree. The tree was marked E1/16 S 5 on North side and E1/16 S 8 on South side.

Marked 2 bearing trees to reference the corner point:
 A 10" ponderosa pine brs S43 $\frac{1}{2}$ ° E, 47.4' scribed E 1/16 S8 BT.
 A 15" ponderosa pine brs N81° E, 72.6' scribed E 1/16 S5 BT.

Measurements to bearing trees are taken from corner point to centerline of bearing trees.
 Corner tree and new bearing trees have a brass washer stamped PLS 1106 nailed to face of blaze. Set steel fence post on National Forest Boundary North of corner and attached sign 54-2. Attached sign 54-9 to the South and North sides of corner tree. Attached sign 54-2 to the West and North sides of corner tree.

Compass declination 18° East.

I hereby certify that the above corner was properly established by me to U.S.F.S. standards and witnessed by Bill Quaempts on August 02, 1989.

REGISTERED PROFESSIONAL LAND SURVEYOR <i>William R. Wells</i> OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

Office of.....County Surveyor.....County of.....Grant
 Oregon
 State of....., I hereby certify that the within instrument was filed in this office
 for record on the 29 day of May, 1990
Robert A. Lopez by
 (COUNTY OFFICIAL) (DEPUTY)