


CORNER RESTORATION

NE Corner
CORNER Sec 13 TWP 10S RANGE 32E., W.M.

ORIGINAL SURVEY BY: Robb and Graddon

CONTRACT NUMBER: 383

CONTRACT DATE: March 26, 1881



ORIGINAL DESCRIPTION:

80.00 North on Range line on East bdy. sec. 13. Var. $22^{\circ}30'$ E.
Set stone 17x10x6 ins. , and built stone mound as per instructions
for cor to secs. 7, 12, 13, and 18, from which
A pine 40 ins. diam.; bears $N23^{\circ}W.$, 169 lks.
A pine 24 ins. diam.; bears $S32^{\circ}E.$, 125 lks.
A pine 38 ins. diam.; bears $S55^{\circ}W.$, 178 lks.

RESTORATION BY, STAMP AND DATE:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Baggett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

July 17, 1975

Grant County Surveyor

EVIDENCE FOUND:

Found the original corner stone, a basalt stone 17x10x7 ins. set in a mound of stone, from which

ORIGINAL BEARING TREES:

The remains of a dead and down pine and stump bears $N19^{\circ}W.$, 111.5 ft.
A pine 15 ins. diam., dead & down bears $S.12^{\circ}E.$, 82.5 ft., with scribing which reads T10S R33E S18 BT.

A pine 24 ins, diam, dead & down, bears $S60^{\circ}W.$, 117.5 ft., scribed T10SR3S13B
~~in scribing which is very weather worn.~~

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set a $1\frac{1}{2}$ "x30" iron pipe with brass cap marked as shown, from which I scribe:

NEW BEARING TREES :

MONUMENT MARKED

A 12 " pine bears $N37^{\circ}E$ 24.8 ft., scribed T10SR33ES7 CSBT.
A 10" pine bears $S16^{\circ}E.$, 10.4 ft., scribed
T10S R33E S18 CS BT.
A 8" pine bears $S53^{\circ}W.$, 21.6 ft., scribed
T10S R32E S13 CS BT.
A 16" pine bears $N55^{\circ}W$ 76.8 ft., scribed
T10S R33E S12 CS BT.

I buried the original cor. stone SE & alongside pipe
Complete and File with Office of the Grant Used compass with $20^{\circ}E.$
County Surveyor, Grant County, Oregon, Var. & steel tape measuring
Courthouse, Canyon City, Oregon 97820 to the face of the blaze
of the BTs.

