

12

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by Robb and Gradon
under General Land Office Contract No. 383.
Surveyor General's records state:
Set post for 1/4 Section Corner
From which:
A fir 28" dia. bears S 60° E, 38 lks. dist.
A fir 4" dia. bears N 15° E, 17 lks. dist.

DIAGRAM

T10 S R33E
1/4 S 14
S 23
1980
PLS 848

Description of corner evidence found:

Found 18"x12"x9" stone set in a circle of stone. Digging under stone,
found old post hole and rotten wood.
From which:
Found a rotten 30" fir stump with log down hill from stump. Part of
blaze with marks visible in logs bears S 60° E, 25.0 ft. This agrees
with record. Accepted post hole as corner position.

Description of monument and accessories I established to perpetuate the
original location of this corner:

Set 30"x3" aluminum pipe with 3 1/2" aluminum cap marked as shown,
24" in the ground and placed ring of stone around pipe.
From which:
A fir 16" dia. bears N 61 1/2° E, 39.7 ft., scribed 1/4 S 14 BT.
A fir 9" dia. bears S 55° E, 9.1 ft., scribed 1/4 S 23 BT.
Nailed brass washers stamped PLS 848 and bearing tree signs to all
bearing trees. Painted red band around all bearing trees.
Set steel fence post 3 ft. West from pipe with warning sign
attached.

Witnesses to the above corner:

J. David Brinton

Phil Negus

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Office of..... Co. Surveyor..... County of..... Grant.....
State of..... Oregon....., I hereby certify that the within instrument was filed in this office
for record on the... 30... day of... Aug... 19... 80...
..... by.....
(COUNTY OFFICIAL) (DEPUTY)