

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by Robb & Gradon
under General Land Office Contract No. 383.
Surveyor General's records state:
Set stone 12x12x8 for 1/4 Section Cor.
from which:
A tamarack 36" dia. bears S 25° E, 32 lks. dist.
A pine 24" dia. bears N 35° W 47 lks dist.

DIAGRAM

T10S R33E
1/4 — S 20
S 29
1980
PLS 848


Description of corner evidence found:

Corner stone not found.
Found a tamarack stump 46" dia., rotten. BT scribing visible.
Bears S 25° E 21 ft. from a point.
Found a rotten pine stump, cut off below scribing. Bears
N 35° W, 31.0 ft. from a point. Said point falls in old
cluster of stone and is accepted as the corner position.

Description of monument and accessories I established to perpetuate the
original location of this corner:


Set 30" x 3" aluminum pipe with 3 1/2" aluminum cap, stamped
as shown, 24" in the ground.
From which:
A fir 8" dia. bears S 45° W, 3.6 ft. scribed 1/4 S 29 BT.
A pine 6" dia. bears N 43° E, 12.5 ft. scribed 1/4 S 20 BT.
Nailed brass washers stamped PLS 848 and bearing tree signs to
all bearing trees. Painted red band around each bearing tree.
Set steel post with warning sign attached, 5 ft. North.

Witnesses to above corner



M. Ferguson

S. Hutchison



Office of... Co. Surveyor... County of... Grant
State of... Oregon... I hereby certify that the within instrument was filed in this office
for record on the... day of... 1980
Robert D. Baggett by
(COUNTY OFFICIAL) (DEPUTY)