

32

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by Robb and Gradon under General Land Office Contract No. 383.

Surveyor General's records state:

Set stone 14"x10"x7" and build stone mound as per instructions for corner to Sections 20, 21, 28, and 29.

From which:

An alder 6" dia. bears N 60° W, 72 lks. dist.

DIAGRAM

T10S	R33E
S 20	S 21
S 29	S 28
1980	
PLS 848	

Description of corner evidence found:

After thorough search of the area, no evidence is found; therefore, corner position is established by proportion.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 30"x3" aluminum pipe with 3 1/2" aluminum cap, stamped as shown, 24" in the ground.

From which:

A pine 14" dia. bears S 4° W, 69.9 ft. scribed T10S, R33E, S 29 BT.

A pine 10" dia. bears S 35° 30' E, 88.5 ft. scribed T10S, R33E, S 28 BT.

Nailed brass washers stamped PLS 848 and bearing tree signs on all bearing trees. Painted red band around all bearing trees.

Set steel fence post 5 ft. West and South with Boundary and Attention signs attached.

Witnesses to the above corner:

~~D. Brinton~~

D. Mitchell Ferguson

P. Negus

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Office of..... Co. Surveyor..... County of..... Grant
Oregon
State of....., I hereby certify that the within instrument was filed in this office
for record on the 20 day of Aug., 1980
Robert D. Sargent by
(COUNTY OFFICIAL) (DEPUTY)