

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by Robb and Gradon under General Land Office Contract No. 383.

Surveyor General records state:

Set stone 12x11x6 for 1/4 cor. from which:

A pine 12 in. dia. bears S 15° W 19 lks. dist.

A pine 15 in. dia. bears N 70° W 28 lks. dist.

DIAGRAM

T10S R33E

1/4 $\frac{S \ 21}{S \ 28}$

1980
PLS 848

Description of corner evidence found:

After a thorough search of the area, no evidence found; therefore, positioned corner by proportion.

Description of monument and accessories established to perpetuate the original location of this corner

Set 30" x 3" aluminum pipe with 3 1/2" aluminum cap, stamped as shown, set 24" in the ground & raised a mound of stone and earth around pipe.

From which:

A pine 10" dia. bears N 34° E, 19.2 ft. scribed 1/4 S 21 BT.

A pine 10" dia. bears S 54° W, 25.0 ft. scribed 1/4 S 28 BT.

Nailed brass washers stamped PLS 848 and bearing tree signs to each bearing tree. Painted red band around each tree.

Set a steel post with warning sign attached, 5 ft. North from corner.

Witnesses to above corner:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Douglas M. Ferguson

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

D. Brinton

P. Negus

Office of Co. Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 20 day of Aug; 1980, at 5 o'clock P.m., (signed)
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)