


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by Robb and Graddon under General Land Office Contract No. 383. Surveyor General's records state:

Set stone 14"x12"x4" in stone mound for 1/4 Section Corner
From which:
A pine 48" dia. bears N 50° E, 20 lks dist.



Description of corner evidence found:



Found a stone 14"x13"x5", 1/4 visible, in remains of an old stone mound.
From which:
A pine 50" dia. bears N 50° E, 14.0 ft. Scribing reads 1/4.

Description of monument and accessories established to perpetuate the original location of this corner:

Set 30"x3" aluminum pipe with 3 1/2" aluminum cap, marked as shown, 14" in ground and raised a mound of stone and earth around pipe.
From which:

A pine 14" dia. bears N 70° W, 44.5 ft. scribed 1/4 S 22 BT.
A pine 14" dia. bears S 43° E, 42.5 ft. scribed 1/4 S 27 BT.
Nailed brass washers stamped PLS 848 and bearing tree signs to all bearing trees. Painted red band around bearing trees.
Set steel fence post 12 ft. East with WARNING and ATTENTION signs attached.

Witnesses to the above corner:



D. Brinton

P. Negus

Office of Co. Surveyor _____ County of Grant
Oregon
State of _____, I hereby certify that the within instrument was filed in this office
for record on the 30 day of Aug, 1980
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)