

59

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by Robb & Gradon under General Land Office Contract No. 383.

Surveyor General's records state:

Set stone 14"x8"x6" for 1/4 Section Corner
From which:

A pine 36" dia. bears N 5° W, 33 lks. dist.

A pine 36" dia. bears S 67° E, 95 lks. dist.

DIAGRAM

T10S R33E

1/4 — S 30.
S 31
1980
PLS 848

Description of corner evidence found:

Found stone 14"x8"x6" marked 1/4 (dim).

From which:

A pine snag 36" dia., scribing visible - 1/4 and Notch - bears
S 67° E, 63.0 ft.

A down pine which fell toward the corner bears N 5° W, 21.8 ft.

No marks visible.

Accepted stone as corner position.

Description of monument and accessories I established to perpetuate the original location of this corner

Set 30" x 3" aluminum pipe with 3 1/2" aluminum cap marked as shown 16" in ground and raised mound of stone and earth around pipe.

From which:

A pine 16" dia. bears N 65° E, 25.0 ft. scribed 1/4 S 30 BT.

A pine 12" dia. bears S 5° W, 46.0 ft. scribed 1/4 S 31 BT.

Nailed brass washers and bearing tree signs to all bearing trees.

Painted red band around bearing trees.

Set steel fence post 5 ft. North with WARNING sign attached.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Witnesses to above corner:

D. Brinton

P. Negus

Office of Co. Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 30 day of Aug, 1980, at 5 o'clock p.m., (signed)
Douglas M. Ferguson by (COUNTY OFFICIAL) (DEPUTY)