

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by Robb and Gradon under General Land Office Contract No. 383.

Surveyor General's records state:

Set stone 16"x10"x7" in stone mound for 1/4

Sec. Corner, from which:

A pine 10" dia. bears S 5° W, 68 lks. dist.

DIAGRAM

T10S R33E

1/4 — S 27
S 34
1980
PLS 848

Description of corner evidence found:

Original stone not found. Found 18" pine, scribing visible, positioned corner at record, N 5° E, 44.9 ft., from bearing tree. Tree in good condition.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 30"x3" aluminum pipe with 3 1/2" aluminum cap, marked as shown, set 18" in the ground and raised mound of stone around pipe.

From which:


A pine 9" dia. bears S 45° W, 32.7 ft., scribed 1/4 S 34 BT.

A juniper 12" dia. bears N 1° W, 42.0 ft., scribed 1/4 S 27 BT.

Nailed brass washers stamped PLS 848 and bearing tree signs to all bearing trees. Painted red band around bearing trees.

Set steel fence post 1 1/2' South in mound of stone with warning signs.

Witnesses to the above corner:



J. David Brinton

P. Negus

Office of... Co. Surveyor... County of... Grant
State of... OREGON... , I hereby certify that the within instrument was filed in this office
for record on the 20 day of Aug, 1980
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)