

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by Robb and Graddon under General Land Office Contract No. 383.

Surveyor General's records state:

Set stone 14"x8"x6" for 1/4 Section Corner, from which:

A tamarack 10" dia. bears N 20° E, 11 lks. dist

A fir 6" dia. bears S 10° W, 17 lks. dist.

DIAGRAM

T10 S R33 E

1/4 — S — 26
 S — 35
 1980
 PLS 848

Description of corner evidence found:

Found 16"x10"x8" stone, set; no marks visible.

From which:

A fir 24" dia. bears S 10° W, 10.5 ft., scribing visible.

A tamarack 11" dia. bears N 30° E, 6.7 ft., scribing visible, 1/4.

Accepted position of the stone as corner position.

Description of monument and accessories established to perpetuate the original location of this corner:

Set 30"x3" aluminum pipe with 3 1/2" aluminum cap marked as shown, set 24" in ground.

From which:

A fir 24" dia. bears S 73 1/2° W, 8.6 ft., scribed 1/4 S 35 BT.

A fir 14" dia. bears N 73° E, 36.6 ft. scribed 1/4 S 26 BT.

Nailed brass washers stamped PLS 848 and bearing tree signs to all bearing trees. Painted red band around all bearing trees.

Set steel fence posts 8' West and 7' North with boundary and warning signs attached.

Witnesses to the above corner:

J. David Brinton

Phil Negus

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Office of... Co. Surveyor... County of... Grant
Oregon
State of... , I hereby certify that the within instrument was filed in this office
for record on the 30 day of Decr... 1980
Robert D. Brinton by _____
(COUNTY OFFICIAL) (DEPUTY)