


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not set by GLO survey

Corner monumented in 1967 by Grant County survey number 63 by Duane I. Griffith...Notes state;

Set iron post 30 ins long 2½ ins dia 24 ins in the ground with brass cap marked (shown below) from which:



A pine 9 ins dia bears S41°E 109 lks dist marked CS 1/16 S31 BT
A pine 16 ins dia bears S75°W 235 lks dist marked CS 1/16 S31 BT

Description of corner evidence found:

Found the brass cap monument and both bearing trees.

I removed the monument and reset it as shown below.

See map of Grant County survey number 928

Description of monument and accessories I established to perpetuate the original location of this corner: At the point determined by survey I reset the monument, a 2½x30" galvanized iron pipe with brass cap marked as shown 28 inches in the ground on the edge of an irrigation ditch, from which;

1967 bearing trees (new bearing and distance)

A 12 inch diameter P.Pine bears S35°E 65.19 feet live and vigorous with scribes visible




A 17 inch diameter P.Pine bears S86°W 24.16 feet live and vigorous with blaze evident

Raised mound of stone around monument

Set steel fenceposts approximately 5 feet West with 54-2 sign and approximately 5 feet East with 54-2 and 54-9 signs attached

Corner reset April 1, 1986

Witnesses: Greg Blackman and Rick Robinson



I used a steel tape and magnetic compass in the establishment of these accessories. I used 20° East magnetic declination and the distances are to a 50d spike driven on the right side of the tree at the root crown.

Office of...*Surveyor*... County of...*Grant*...
State of...*Oregon*... I hereby certify that the within instrument was filed in this office
for record on the...*29* day of...*April*... 19...*86*...
Robert D. Dyer by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

☆U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276

SEE REMOVAL FILED
Nov 29, 1967