

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. E-15.

History of original corner establishment:

Corner was originally established by Herman D. Gradon under GLO contract No. 416 during October, 1881. Surveyors General's notes state: "Set a basalt stone 16x8x6 ins. 11 ins. in the ground for 1/4 sec. cor. marked 1/4 on N face: from which: A fir 16 ins. diam. bears N60°E, 50 lks. dist. marked 1/4S BT. A tamarack 12 ins. diam. bears S60°E, 26 lks. dist. marked 1/4S BT."

DIAGRAM

T10S R35E
S3
1/4 —+—
S10

Description of corner evidence found:

Found 18x10x8 inch stone firmly set and clearly marked 1/4 in north face, From which: A down and rotten fir bears N70°E, 32.5 ft. with 1/4 visible. Rotten remains of stump bears S59°E, 18.4 ft.

Description of monument and accessories established to perpetuate the original location of this corner:

T10S R35E
S3
1/4 —+—
S10
OR PLS 1051
1980

At the center of the above stone set 2 1/2" X 30" galvanized pipe and brass cap marked: Set pipe 25" in the ground and mound of stone around to cap. Placed marked stone at base of pipe.

From which by magnetic declination of N20°E;

A 16" lodgepole pine bears S16°W, 25.2 ft. scribed 1/4S10 BT. A 16" tamarac bears N20°W, 103.5 ft. scribed 1/4S3 BT. Painted blazes red and 6" red band around. Placed 54-3s, 54-4s and brass washers stamped PLS 1051 on BTs. Placed 54-4 on steel fence post 5' west of the corner.

I hereby certify that the above corner monument was reestablished as herein described,

Witnesses: Daniel Rowland
Doug Moser

October 22, 1980

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Barry B. Barbours

OREGON
OCT. 17, 1975
BARRY B. BARBOURS
1051

Office of.....County Surveyor..... County of.....Grant.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the.....28th day of.....January....., 19.....81
.....Robert D. Beyer..... by
(COUNTY OFFICIAL) (DEPUTY)