


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. J-7

History of original corner establishment:

Corner was originally established by Herman D. Gradon under GLO contract No. 416 during October, 1881. Surveyor General's notes state: "Set a quartz stone 16x14x10, 11 ins. in the ground, for 1/4 sec. cor. marked 1/4 on N. face: from which: A balck pine 6 ins. diam. bears N70°W, 36 lks. dist. marked 1/4 on S BT. A Fir 30 ins. diam. bears S75°E, 280 lks. dist. marked 1/4S BT.



Description of corner evidence found:

Found 17x 17x10 inch stone clearly marked 1/4 from which: A 36" fir bears S77°E, 186.6 ft. to centerline scribed "1/4". A 16" lodgepole pine bears N66°W, 25.1 ft. with partially opened blaze and no visible scribing. Due to sluffing blaze almost covered with dirt.

Corner falls about 250' south of jeep trail.

Description of monument and accessories I established to perpetuate the original location of this corner:



At center of the above point set 2 1/2" X 30" galvanized pipe and brass cap marked: Set pipe 24" in the ground and mound of stone around to cap. Placed marked stone alongside. From which by magnetic declination of N20°E; A 30" pine bears N08°E, 119.6 ft. scribed 1/4S8 BT. Painted blazes red and 6" red band around. Placed 54-3s and 54-4s on old and new BTs. Placed brass washers stamped PLS 1051 on new BT. Placed 54-4 on steel fence post 5' west of the corner.

T10S R35E
S8
1/4 ———
S17
OR PLS1051
1980

I hereby certify that the above corner monument was reestablished as herein described,

Witnesses: Daniel Rowalnd

September 12, 1980



Office of.....County Surveyor.....County of.....Grant.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the 20th ²³ day of January....., 1981.
.....by.....
(COUNTY OFFICIAL) (DEPUTY)