CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: *

The original corner was set in 1881 by Rufus S. Moore under Contract No. 382, dated March 23, 1881.
The original notes state:
S 0°18′ East on a true line
39.85 Set a pine post from which
A pine 24 ins dia bears N 60° E, 28 lks
A pine 22 ins dia bears N 73° W, 32 lks

DIAGRAM
T10S R32E
1/4
S2|S1

Description of corner evidence found:

At record distance and direction from the original bearing trees found wood fragments in a mound of stone.
A 20" cut Pine stump bears N 60¾° E, 18.7 ft (N 60° E, 28 lks), notch in a loose face.
A deteriorated Pine stump bears N 75-3/4° W, 20.6 ft to face (N 73° W, 32 lks), small face and ax mark remaining.

Description of monument and accessories I establish to perpetuate the original location of this corner:

Set a 2½x28" aluminum monument 20" in the ground in a mound of stone.
I establish new bearing trees:
A 5" P.Pine bears N 23¾° E, 27.1 ft, scribed 1/4S1BT.
A 9" P.Pine bears N 51¾° W, 42.8 ft, scribed 1/4S2BT.

T10S R31E
1/4
S2|S1
PLS1918
1988

New BTs have 3/4" brass washers marked PLS1918 attached to the BT blaze, faces and bands painted with red tree marking paint, and BT tags and Attention or Land Survey Monument signs. A steel fence post with Attention or Land Survey Monument sign is driven approximately 3-5 feet from the corner.

Sun Cadastral Survey, Cont No. 53-04H1-7-4011
Field Book: 4-15 & 5-36
Work accomplished: 7/31/88
Witnesses: Tyler Parsons, Louise Parsons
Sharon Parsons, Douglas Parsons
Job No.: 8722I

PARSONS SURVEYING
1915 S.E. Stone Street
Corvallis, OR 97333
(503) 752-7515

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Tyler B Parsons
OREGON
JULY 18, 1980
TYLER B. PARSONS
1918

Office of COUNTY SURVEYOR County of GRANT
State of OREGON , I hereby certify that the within instrument was filed in this office for record on the 17th day of Feb, 1989

Robert D Bryant by _____
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)