J-23

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

The corner was established by H. Gradon in 1881 under Contract No. 383. The original notes state:

S89°52'W on true line between Secs 12 & 13
40.25 Set stone 22x8x5 in stone mound for 1/4 sec cor

DIAGRAM
T10S R32E
S12
1/4---
S13

Description of corner evidence found:

Found no evidence of the original corner.

Description of monument and accessories I establish to perpetuate the original location of this corner:

Reestablish this corner by single proportion. Set a 2/1-2x30" aluminum monument 18" in the ground in a mound of stone.
New BTs:
A 15" Pine bears S66°57'E 44.0 ft scribed 1/4S13BT.
A 13" Pine bears N46°52'E 64.5 ft scribed 1/4S12BT.

T10S R32E
S12
1/4---
S13
PLS1918
1989

New BTs have 3/4" brass washers marked PLS1918 attached to the BT blaze, faces and bands painted with red tree marking paint, and BT tags and Attention or Land Survey Monument signs. A steel fence post with Attention or Land Survey Monument sign is driven approximately 3-5 feet from the corner.

Sun Cadastral Survey
Contract No.: 53-04H1-7-4011
Project No.: 8722LB
Field Book: 7-73
Work Accomplished: 6/8/89
Witnesses: Louise Parsons

PARSONS SURVEYING
1915 S.E. Stone Street
Corvallis, OR 97333
(503) 752-7515

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Tyler B Parsons
OREGON
JULY 18, 1980
TYLER B. PARSONS
1918

Office of COUNTY SURVEYOR County of GRANT
State of OREGON, I hereby certify that the within instrument was filed in this office for record on the 10 day of Aug, 1989

Robert A Bagett by _____
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

J-23
CS1095