R-23

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

The corner was established by H. Gradon in 1881 under Contract No. 383. The original notes state:

S89°49'W on true line between Secs 24 & 25
40.39 Set post for 1/4 Sec cor from which
A tamarack 15 in dia bears N40°W 32 lks dist
A pine 15 in dia bears S67°W 58 lks dist.

DIAGRAM
T10S R32E
S24
1/4---
S25

Description of corner evidence found:

Found no evidence of the original corner.

Description of monument and accessories I establish to perpetuate the original location of this corner:

Reestablish this corner by single proportion.
Set a 2-1/2x30" aluminum monument 22" in the ground.
New BTs:
A 6" Fir bears S14°50'W 17.0 ft scribed 1/4S25BT.
A 9" Fir bears N21°12'E 39.0 ft scribed 1/4S24BT.

T10S R32E
S24
1/4---
S25
PLS1918
1989

New BTs have 3/4" brass washers marked PLS1918 attached to the BT blaze, faces and bands painted with red tree marking paint, and BT tags and Attention or Land Survey Monument signs. A steel fence post with Attention or Land Survey Monument sign is driven approximately 3-5 feet from the corner.

Sun Cadastral Survey
Contract No.: 53-04H1-7-4011
Project No.: 8722LB
Field Book: 7-71
Work Accomplished: 6/7/89
Witnesses: Louise Parsons

PARSONS SURVEYING
1915 S.E. Stone Street
Corvallis, OR 97333
(503) 752-7515

REGISTERED
PROFESSIONAL
LAND SURVEYOR
OREGON
JULY 18, 1980
TYLER B. PARSONS
1918

Office of COUNTY SURVEYOR County of GRANT
State of OREGON , I hereby certify that the within instrument was filed in this office for record on the 10 day of Aug, 19 89

Robert D Bagett by _____
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

R-23
CS1095