


CORNER RESTORATION

CORNER N ¼ Corner
Sec. 20 TWP 11 S RANGE 26 E

ORIGINAL SURVEY BY: Aaron F. York

CONTRACT NUMBER: 371

CONTRACT DATE: October 27, 1880



ORIGINAL DESCRIPTION:



West on True Line (Between Secs. 17 & 20)

40.05 set stone 12x11x6 for ¼ Sec. cor.

Raised stone mound at corner.

RESTORATION BY, STAMP AND DATE:

D. I. Griffith
K. Leckenby



April 25, 1979

Grant County Surveyor.

EVIDENCE FOUND:

Found stone 12"x10"x3" mkd. ¼ Set in ground.

See Map of Survey No. 571.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

MONUMENT MARKED

I accept the position of the corner stone.

At the corner point: Set 1½"x30" iron pipe in the ground with brass cap marked as shown. I buried the corner stone alongside the iron pipe and surrounded the pipe with a mound of stone.

No bearing trees available.

RECEIVED AND
FILED

AUG 31 1979

JOHN LIVEIRA, County Clerk

By Sammie Lawrence Deputy

