


# CORNER RESTORATION

CORNER E  $\frac{1}{4}$  Cor.  
Sec. 20 TWP 11 S. RANGE 26 E.

ORIGINAL SURVEY BY: Aaron F. York

CONTRACT NUMBER: 371

CONTRACT DATE: October 27, 1880



## ORIGINAL DESCRIPTION:

North on line between Secs. 20 & 21.

40.00 set stone 36x24x20 for  $\frac{1}{4}$  Sec. cor.

Raised stone mound at corner.

## RESTORATION BY, STAMP AND DATE:

D. I. Griffith  
K. Leckenby

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Robert D. Bagett*  
OREGON  
JULY 12, 1963  
ROBERT D. BAGETT  
598

April 25, 1979

Grant County Surveyor

## EVIDENCE FOUND:

Found stone 38"x23"x18" mkd.  $\frac{1}{4}$  on the East side and set in a mound of stone.

See Map of Survey #571.

## DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.


I accept the position of the corner stone. At the corner point: Set 1 $\frac{1}{2}$ "x30" iron pipe in the ground with brass cap marked as shown. I buried the corner stone West and alongside the iron pipe, and surrounded the pipe with a mound of stone, from which I scribe:

### NEW BEARING TREES:

A 12" Juniper bears N. 30° E., 30.5 ft. mkd.  $\frac{1}{4}$ S21CSBT.  
A 6" Juniper bears S. 29° W., 46.5 ft. mkd.  $\frac{1}{4}$ S20CSBT.

I used a magnetic compass with 20° East variation and steel tape, measuring to the center of the bearing trees.

## MONUMENT MARKED



RECEIVED AND  
FILED

AUG 31 1979

JOHN LIVEIRA, County Clerk

*Limmie L. Luragay*  
County Clerk