


CORNER RESTORATION

SW Corner
CORNER Sec. 20 TWP 11 S RANGE 26 E

ORIGINAL SURVEY BY: Aaron F. York

CONTRACT NUMBER: 371

CONTRACT DATE: October 27, 1880



ORIGINAL DESCRIPTION:

North on line bet. Secs. 29 & 30.
80.00 set stone 17x13x9 for corner to Secs. 19, 20, 29 & 30.
Raised stone mound at corner.

RESTORATION BY, STAMP AND DATE:

D. I. Griffith
K. Leckenby

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett
OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

May 8, 1979 Grant County Surveyor.

EVIDENCE FOUND:

Found stone 14"x8"x7" marked and set in a mound of stone.

See Map of Survey No. 571.


DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:
Show how trees are scribed and basis of bearings, including compass var.

I accept the position of the corner stone.
At the corner point: Set 1½"x30" iron pipe in ground with brass cap marked as shown. I buried the corner stone South and alongside the iron pipe and surrounded the pipe with a mound of stone, from which I scribe
NEW BEARING TREES:

An 8" Juniper bears S. 33° E., 16.5 ft. mkd. T11SR26ES29CSBT
A 10" Juniper bears N. 46 ° W., 112.8 ft. mkd. T11SR26ES19CSBT

I used a magnetic compass with 20° East variation and steel tape measuring to the center of the bearing trees.

MONUMENT MARKED



RECEIVED AND
FILED

AUG 31 1979

JOHN LIVEIRA, County Clerk

Sammie Lawrence
Deputy