


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established



Description of corner evidence found:

NONE

Description of monument and accessories I established to perpetuate the

original location of this corner: At the corner position, I set a 2½" x 30" aluminum pipe with a National Park Service aluminum cap marked as shown, 24 inches in the ground, with a 6 inch diameter concrete collar, from which:

A 9 inch diameter Juniper bears South 20° West, 83.9 feet, marked W1/16 S29 BT




No bearing tree available North

Set steel fence posts approximately 5 feet South and East of the corner

Painted blazes and a 6 inch red band around the bearing tree

Corner set November 11, 1983

Witnesses: Greg Blakeman and Rick Robinson



I used a steel tape and magnetic compass in the establishment of accessories. I used 20° East magnetic declination, and the distance to the bearing tree is to the center of the tree. I placed a brass washer marked OPLS 644 by the BT blaze of the new BT.

Office of... Surveyor ... County of... Grant ...
State of... Oregon ... , I hereby certify that the within instrument was filed in this office
for record on the... 15 ... day of... August ... , 19... 84 ...
Robert D. Bayart ... by ...
(COUNTY OFFICIAL) (DEPUTY)