


CORNER RESTORATION

W $\frac{1}{4}$ Corner
CORNER Sec. 29 TWP 11 S RANGE 26 E

ORIGINAL SURVEY BY: Aaron F. York

CONTRACT NUMBER: 371

CONTRACT DATE: October 27, 1880



ORIGINAL DESCRIPTION:

North on line between Secs. 29 & 30.

40.00 set stone 12x10x8 for $\frac{1}{4}$ sec. cor.

Raised stone mound at corner.

RESTORATION BY, STAMP AND DATE:

D. I. Griffith
K. Leckenby

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Baggett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

April 30, 1979

Grant County Surveyor.

EVIDENCE FOUND:

Found stone 12"x10"x8" mkd. $\frac{1}{4}$ set in stone mound.

See Map of Survey No. 571.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.


MONUMENT MARKED

I accept the position of the corner stone.

At the corner point: Set 1 $\frac{1}{2}$ "x30" iron pipe in ground with brass cap marked as shown. I buried the corner stone South and alongside the iron pipe and surrounded the pipe with a mound of stone, 6 ft. diam., 4" high, from which I scribed NEW BEARING TREE:

A 14" Juniper bears N. 82° E., 83.0 ft. mkd. $\frac{1}{4}$ S29CSBT.

I used a magnetic compass with 20° East variation and steel tape, measuring to the center of the bearing tree



RECEIVED AND
FILED

AUG 31 1979

JOHN LIVEIRA, County Clerk

Amie Lawrence Deputy

T-5