


CORNER RESTORATION

^E/₄ Cor.
CORNER Sec. 29 TWP 11 S. RANGE 26 E.

ORIGINAL SURVEY BY: Aaron F. York

CONTRACT NUMBER: 371

CONTRACT DATE: October 27, 1880



ORIGINAL DESCRIPTION:

North on line bet. Secs. 28 & 29.

40.00 set stone 10x10x6 for ¹/₄ Sec. cor.

Raised stone mound at corner.

RESTORATION BY, STAMP AND DATE:

D. I. Griffith
K. Leckenby

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Baggett

OREGON
JULY 12, 1963
ROBERT D. BAGGETT
598

April 28, 1979

Grant County Surveyor.

EVIDENCE FOUND:

Found stone of call size marked ¹/₄ and set in a mound of stone.

See Map of Survey No. 571.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

I accept the position of the corner stone.

MONUMENT MARKED


At the corner point: Set a 1¹/₂"x30" iron pipe in the ground with brass cap marked as shown. I buried the corner stone West and alongside the iron pipe and surrounded the pipe with a mound of stone, from which I scribe

NEW BEARING TREES:

A 29" Juniper bears N. 68° E., 120.0 ft. mkd. ¹/₄S28CSBT.

A 16" Juniper bears N. 23° W., 46.6 ft., mkd. ¹/₄S29CSBT.

I used a magnetic compass with 20° East variation and steel tape, measuring to the center of the bearing trees.



RECEIVED AND
FILED

AUG 31 1979

JOHN LIVEIRA, County Clerk

By *Sammy Laur* Deputy