


CORNER RESTORATION

CORNER S ¼ corner
Sec. 29 TWP 11 S RANGE 26 E

ORIGINAL SURVEY BY: Aaron F. York
CONTRACT NUMBER: 371
CONTRACT DATE: October 27, 1880



ORIGINAL DESCRIPTION:

West on true line (between Secs. 29 & 32)

39.98 set stone 14x10x6 for ¼ sec. cor.

Raised stone mound at corner.

RECEIVED AND
FILED

SEP 18 1979

JOHN LIVEIRA, County Clerk

By Lamoria Laura Deputy

RESTORATION BY, STAMP AND DATE:

D. I. Griffith
K. Leckenby

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

April 28, 1979

Grant County Surveyor.

EVIDENCE FOUND:

No evidence, I established the S ¼ corner sec. 29 at the midpoint and on the line between the Southwest and Southeast corners of Section 29.

See Map of Survey No. 571.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:


Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set 2½"x30" aluminum pipe with National Park Service aluminum cap marked as shown. I surrounded the aluminum pipe with a concrete collar and a mound of stone, from which I scribed NEW BEARING TREES:

A 7" Juniper bears N. 85° E., 61.4 ft. mkd. ¼ S29CSBT.
A 10" Juniper bears S. 28° W., 12.2 ft. mkd. ¼ S32CSBT.

I used a magnetic compass with 20° East variation and steel tape, measuring to the center of the bearing trees.

STANDARD NATIONAL PARK SERVICE
MONUMENT MARKED



Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820