


CORNER RESTORATION

SE Corner
CORNER Sec. 29 TWP 11 S RANGE 26 E

ORIGINAL SURVEY BY: Aaron F. York

CONTRACT NUMBER: 371

CONTRACT DATE: October 27, 1880




ORIGINAL DESCRIPTION:


North on line between Secs. 32 & 33.
80.00 set stone 18x10x6 for corner to Secs. 28, 29, 32 & 33.
Raised stone mound at corner.

RESTORATION BY, STAMP AND DATE:

D. I. Griffith
K. Leckenby



Robert D. Baggett



April 28, 1979 Grant County Surveyor

EVIDENCE FOUND:

Found stone 17"x9"x7" mkd. with 5 notches and 2 notches set in a mound of stone.

See Map of Survey No. 571.


DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:
Show how trees are scribed and basis of bearings, including compass var.

I accept the position of the corner stone. At the corner point: Set 1½"x30" iron pipe in the ground with brass cap marked as shown. I buried the corner stone South and alongside the iron pipe and surrounded the pipe with a mound of stone, from which I scribe
NEW BEARING TREES:

A 24" Juniper bears N. 43° W., 54.1 ft. mkd. T11SR26ES29CSBT.
A 7" Juniper bears N. 83° E., 116.0 ft. mkd. T11SR26ES28CSBT.

I used a magnetic compass with 20° East variation and steel tape, measuring to the center of the bearing trees.

MONUMENT MARKED



RECEIVED AND
FILED

AUG 31 1979

JOHN LIVEIRA, County Clerk
By *Lennie Lawrence* Deputy