


CORNER RESTORATION

CORNER E¹/₄ Cor. TWP 11 S. RANGE 26 E
Sec. 32

ORIGINAL SURVEY BY: Aaron F. York

CONTRACT NUMBER: 371

CONTRACT DATE: October 27, 1880



ORIGINAL DESCRIPTION:

North on line bet. Secs. 32 & 33.

40.00 set stone 20x12x8 for $\frac{1}{4}$ Sec. corner.
Raised stone mound at corner.

RESTORATION BY, STAMP AND DATE:

D. I. Griffith
K. Leckenby

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Baggett

OREGON
JULY 12, 1973
ROBERT D. BAGGETT
598

April 29, 1979

Grant County Surveyor

EVIDENCE FOUND:

No evidence, I established the E¹/₄ corner Section 32 at the mid-point and on the line between the Northeast and Southeast corners of Section 32.

See Map of Survey #571.


DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set a 1 $\frac{1}{2}$ "x30" iron pipe in the ground with brass cap marked as shown. I surrounded the pipe with a mound of stone.

No bearing trees available.

MONUMENT MARKED



RECEIVED AND
FILED

AUG 31 1979

JOHN LIVEIRA, County Clerk

By *Lennie Lawrence* Deputy