


CORNER RESTORATION

CORNER ^{SE corner} Sec. 32 TWP 11 S RANGE 26 E

ORIGINAL SURVEY BY: W. Byars
CONTRACT NUMBER: 185
CONTRACT DATE: May 7, 1873



ORIGINAL DESCRIPTION:

South 89° 45' West on a true line between Secs. 4 and 33.
80.00 set corner to Secs. 4, 5, 32 and 33.
A stone 18x8x6.

RECEIVED AND
FILED

SEP 18 1979

JOHN LIVEIRA, County Clerk

Samuel Lawrence

RESTORATION BY, STAMP AND DATE:

D. I. Griffith
R. D. Bagett

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

April 29, 1979

Grant County Surveyor.

EVIDENCE FOUND:

Found stone 20x9x6 marked and set in a mound of stone.

See Map of Survey No. 571.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

STANDARD NATIONAL PARK SERVICE.
MONUMENT MARKED

I accept the position of the corner stone.

At the corner point: Set 2½"x30" aluminum pipe with National Park Service aluminum cap marked as shown. I buried the corner stone West and alongside the aluminum pipe and surrounded the pipe with a concrete collar and a mound of stone, from which I scribed NEW

BEARING TREES:

A 7" Juniper bears N. 36° E., 28.5 ft. mkd. S33BT.
A 9" Juniper bears S. 31° E., 12.6 ft. mkd. T12SR26E S4BT.
A 6" Juniper bears S. 69° W., 23.7 ft. mkd. S5BT.
A 6" Juniper bears N. 49° W., 50.2 ft. mkd. S32BT.

Complete and File with Office of the Grant County Surveyor, Grant County, Oregon, Courthouse, Canyon City, Oregon 97820

I used a magnetic compass with 20° East variation and steel tape, measuring to the center of the bearing trees.

