

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. P-13

History of original corner establishment:

Corner is originally established by
Aaron F. York, in 1880, under "General
Land Office" Contract No. 371.
Surveyor Generals Notes State:
Set Stone 10x10x8 for 1/4 Sec. Cor.
Raised Stone mound at Cor.

DIAGRAM

T11S R28E
1/4
S211S22
1986
RLS 848

Description of corner evidence found:

No evidence is found, corner falls in an area
which has been logged. Examined all the stones in
the area.

No accessories originally established.
Set corner position at proportionate measure,
between corners found 1/2 mi. North and South.
The proportioned position bears S10°13'E.,
7.23 ft. from an approx. corner as established
by Jack Shaw, around 1960.

Description of monument and accessories | established to perpetuate the
original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown
on the **DIAGRAM**, SET 20" in the ground.
From Which:
A Fir 9" dia., Bears N27°W., 9.8 ft., scribed: 1/4 S21 BT
A Fir 7" dia., Bears N17°E., 31.0 ft., scribed: 1/4 S22 BT
Measurements to trees taken with a metal tape and magnetic compass,
with Declination set off 20 deg. East.
Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing
Tree Sign above blaze, and warning sign on back of each tree. Painted
a 6" red band at breast ht. around each tree. Set steel fence posts with
warning & Boundary Signs, South & East 5 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: Nov. 8, 1986
Refer to Map of Survey No. 965

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*....., I hereby certify that the within instrument was filed in this office
for record on the.....*18* day of.....*April*....., 19*86*
Robert D. Bogan by.....
(COUNTY OFFICIAL) (DEPUTY)