


CORNER RESTORATION

CORNER S $\frac{1}{4}$ TWP 11S RANGE 29E

ORIGINAL SURVEY BY: William H. Byars

CONTRACT NUMBER: UNK

CONTRACT DATE: 1873



ORIGINAL DESCRIPTION:

Set stone 14"x 12"x 6"

Fd. in retracment by William R Gradon in 1884.

RESTORATION BY, STAMP AND DATE:

BAGETT & GRIFFITH SURVEYING
 170 S. DAYTON - PH. 575-1251
 JOHN DAY, OREGON 97845



July 1969

EVIDENCE FOUND:

NONE

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set 2 $\frac{1}{2}$ "x 30" iron post with brass cap.

From which:

A: pine 36"diam. bears N2W; 36.6 ft.

Mkd $\frac{1}{4}$ S32 BT

A fir 10"diam. bears N63E; 41.5 ft.

Mkd $\frac{1}{4}$ S32 BT

MONUMENT MARKED

GRANT COUNTY SURVEYOR

$\frac{1}{4}$ S 32

1969

LS 644

Complete and File with Office of the Grant
 County Surveyor, Grant County, Oregon,
 Courthouse, Canyon City, Oregon 97820

Steel tape & compass
 Var = 20° East