CORNER RESTORATION



CORNER SW Sec. 35 TWP 11S RANGE 29E

ORIGINAL SURVEY BY: William H. Byars

CONTRACT NUMBER: Unknown

CONTRACT DATE: 1873

ORIGINAL DESCRIPTION:

Set stone 14"x10"x8"
Found in survey by William R. Gradon in 1884

RESTORATION BY, STAMP AND DATE: June, 1970

REGISTERED
OREGON
LAND SURVEYOR

JULY 10, 1964
DUANE I. GRIFFITH
644

EVIDENCE FOUND:

Found stone 14"x10"x8" with notches in a mound of stone.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:
Show how trees are scribed and basis of bearings, including compass var.

Set 1½"x30" iron post with Brass Cap mkd.:
From which:
A pine 10" diam. bears N58°W, 45.0 ft.
Mkd. T11S R29E S34 BT
A pine 7" diam. bears N52°E, 6.1 ft.
Mkd. T11S R29E S35 BT

MONUMENT MARKED

Grant County Surveyor
T11S R29E
S34 | S35
S3
T12S R29E
1970
LS 644

Steel tape & Compass
Var.=20°East

Complete and File with Office of the Grant County Surveyor, Grant County, Oregon, Courthouse, Canyon City, Oregon 97820

Z-17