

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by S.W. Lackland, Under General Land Office Contract No. 415. Surveyor General's Notes State: 76.50 ch. intersected N boundary of Twp 2.53 chs. East of corner to sections 35 & 36, T10S R30E which is a basalt stone 14x10x7" marked 1 notch on E and 5 notches on W edges. Repaired corner by raising mound of stone.

At which point I set a basalt stone 16x7x7" 12" in ground for C corner to section 1 & 2, marked with 1 notch on E, & 5 notches on S face, raised a mound of stone 2½" high 5 ft. base alongside.

DIAGRAM

T10S R30E
CC
S2 | S1
T11S
1983
PLS848

Description of corner evidence found:

Found a 16x8x7" stone with CC visible, lying loose on South side of old mound of stone. When the corner is placed on the North side of old mound of stone (3.9 ft. N & 2.5 ft W from where it is found) it falls on TWP. line at record distance from the standard corner to the West, therefore that position is accepted as the closing corner to sections 2/1.

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 30"x2" aluminum cap stamped as shown in diagram.

Set 14" in ground, placed original stone North alongside pipe & raised a mound of stone around pipe & original stone.

From which:

A Pine 9" dia. bears S37°E, 21.2 ft. scribed T11S R30E CC S1 BT.



A Juniper 8" dia. bears S22°W, 35.4 ft. scribed T11S R30E CC S2 BT.

Set a steel post with warning & boundary sign West 11 ft. & East 5 ft.

Nailed brass washers stamped PLS848, bearing tree & warning signs to each tree.

Corner Monumented 6-2-83

Witnessed by Dan Martin



Office of.....Surveyor..... County of.....Grant.....

State of.....Oregon....., I hereby certify that the within instrument was filed in this office

for record on the 29th day of.....August....., 1983.

.....Robert V. Bayett..... by.....
(COUNTY OFFICIAL) (DEPUTY)