

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. D-9

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

In 1909, Micheal Spears, County Surveyor, Subdivided this Section 4, whereby he set a temporary corner at this 1/16, but did not finally establish the corner. See Survey Record Book 1, Page 25.

DIAGRAM

T11S R30E
S1/16
S5/16
1986
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.
(See "History of original corner established" above.)

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe, with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, Set 28" in the ground, 2 ft. West from a N-S-E fence corner.

From Which:

A Juniper 6" dia., Bears N 1⁰W., 34.0 ft., scribed: S1/16 S5 BT

A Juniper 14" dia., Bears East, 24.2 ft., scribed: S1/16 S4 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe & Bearing Tree Sign above blaze,

Painted a 6" red band at breast ht. around each tree.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: May 8, 1986
Refer to Map of Survey No. 934

Office of.....*Sumner*..... County of.....*Grant*.....
State of.....*Oregon*....., I hereby certify that the within instrument was filed in this office
for record on the.....*20*..... day of.....*June*....., 19.....*86*.....
.....*Robert D. Baggett*..... by.....
(COUNTY OFFICIAL) (DEPUTY)