

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. D-13

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

In 1909, Micheal Spears, County Surveyor, Subdivided this Section 4, whereby he set a temporary corner at this 1/16, but did not finally establish the corner. See Survey Record Book 1, Page 25.

DIAGRAM

T11S R30E
S1/16
S41S3
RM120.0
1986
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.
(See "History of original corner established" above.)

Description of monument and accessories | established to perpetuate the original location of this corner:

Corner falls in roadway, set 5/8"x30" iron pin with plastic cap stamped: PLS 848 SURVEY MARKER, 2" under road surface.
From Which:
Set 2-1/2"x30" aluminum pipe, with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, Set 24" in the ground for a Reference Monument,
Bears N 0°26'32"E, on the Section Line, 20.00 ft.,
A Juniper 16" dia., Bears N71°14'E., 47.6 ft., scribed: S1/16 S3 BT
A Juniper 14" dia., Bears N17°35'W., 106.9 ft., scribed: S1/16 S4 BT
Measurements to Accessories taken with Electronic Tacheometer, with angles turned from the survey control network.
Nailed a brass washer stamped PLS 848 on blaze above BT scribe & Bearing Tree Sign above blaze,
Painted a 6" red band at breast ht. around each tree.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: May 9, 1986
Refer to Map of Survey No. 934

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 9th day of June, 1986
Robert D. Sagett by _____
(COUNTY OFFICIAL) (DEPUTY)