

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by S.W. Lackland, Under General Land Office Contract No. 415. Surveyor Generals Notes state: N89°43'E on true line between sections 4 & 40.13 ch, set basalt stone 15x8x6" 10" in ground for ¼ section corner marked ¼ on N face Raised a mound of stone alongside. (Note this line is closing on subdivision by W.H. Byers, in 1873.) April 1, 1909 Micheal Spears, Grant county Surveyor found the corner in good condition.

DIAGRAM


T11S R30E
S4
¼ ——— S9
1983
PLS848

Description of corner evidence found:

No evidence found, old E & S rail fence corner N40°E, 45' from corner examined all stones at call size in the area.
No accessories originally established.


Description of monument and accessories | established to perpetuate the original location of this corner:

Set a 30"x2" aluminum pipe with a 3½" aluminum cap stamped as shown in diagram. Set 6" in ground & raised a mound of stone & earth around pipe.
From which:
A Juniper 8" dia. bears S35°E, 59.3 ft. scribed ¼ S9 BT.
A steel post with warning sign bears North 13.6 ft.
Nailed brass washers stamped PLS848, bearing tree & warning signs to each tree.



Corner monumented 7-27-83

Witnessed by Jeff Smith.



Office of...Surveyor..... County of...Grant.....
State of...Oregon....., I hereby certify that the within instrument was filed in this office
for record on the 29th day of August, 1983.
Robert D. Basm by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

SUPERSEDED BY
REMON SHEET FILED
JUNE 20, 1986
SE SURVEY NO. 934

☆ GPO—798-276

E-11