

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. N-9

History of original corner establishment:

Corner was originally established by W.H. Byars, in Aug., 1873, under General Land Office Contract No. 197. U.S. Surveyor Generals Notes State: Set a Basalt stone 12x10x8 for the corner to Sections 16-17-20 and 21

In Sept. 1881, S.W. Lackland, under General Land Office Contract No. 415, intersected the line. Those Notes State: intersected N-S line at 58 lks N. of cor. 16,17,20 & 21, which is a stone 12x8x10 ins. repaired same by raising a mound of stone.

DIAGRAM

T11S R30E
S17:S16
-.-
S20:S21
1986
PLS 848

Description of corner evidence found:

The original stone is not identified, there is a N-S-E-W fence corner just SW from the corner and there has been a lot of fencing activity over the years. The corner stone has been displaced by the fencing. There is no call for any accessories by the original notes. Found a 40" Pine with scribing: T11S R30E S16 Bears NE from the corner area. The tree is ring counted and the blaze is over 100 years old. This looks like a S.W. Lackland tree. Lackland apparently did not record this tree. The corner position is determined by proportionate measure from corners found 1 mi. North, 2 mi. South, 1/2 mi. East & 1.5 mi. West. This position is facing the tree blaze approx. 60 ft.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 20" in the ground and placed a circle of stone filled with earth around of the pipe.

From Which:

A Juniper 10" dia., Bears N58°W., 20.2 ft., scribed: T11S R30E S17 BT
A Juniper 9" dia., Bears N34°E., 24.6 ft., scribed: T11S R30E S16 BT
A Juniper 12" dia., Bears S70°E., 19.8 ft., scribed: T11S R30E S21 BT
A Juniper 7" dia., Bears S29°W., 15.0 ft., scribed: T11S R30E S20 BT
Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.
Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, North & South 6 ft. from the corner.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

**OREGON
JULY 12, 1989
DOUGLAS M. FERGUSON
848**

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: Sept. 2, 1986
Refer to Map of Survey No. 955

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*..... I hereby certify that the within instrument was filed in this office
for record on the.....*18*..... day of.....*Dec*....., 19*86*.....
.....*Robert D. Bryant*..... by.....
(COUNTY OFFICIAL) (DEPUTY)