

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. R-9

History of original corner establishment:

Corner was originally established by
W.H. Byars, in Aug., 1873, under
General Land Office Contract No. 197.
U.S. Surveyor Generals Notes State:
Set a Basalt stone 14x12x8 for the Cor
to Sections 20-21-28 & 29

DIAGRAM

T11S R30E
S201S21
-.-
S291S28
1986
PLS 848

In Sept. 1881, S.W. Lackland, under
General Land Office Contract No. 415,
intersected the line. Those Notes State:
intersected N-S line at 52 lks N. of cor.
to Secs 20,21,28 & 29, Which is a Basalt
stone 14x12x8 ins. marked 2 notches on S
& 4 notches on E edges. Repaired same by
raising mound of stone.

Description of corner evidence found:

Found a mound of stone which was not accepted as the
Corner as it did not fit surrounding evidence and
there are no marks or conclusive evidence. This
mound falls approx. 60 ft. south of proportion locus.
There are no accessories originally established,
except the mound of stone as placed by S.W. Lackland.
There is an old N-E & W fence corner Northeast 20 ft.
from the Proportioned corner position, the corner
is lost to fencing activity over the years.
Accepted the proportioned position as measured
from Corners found 2 mi. North, 1 mi. South,
1 mi. East and 1/2 mi. West.
(See referenced Map of Survey No. 955)

**Description of monument and accessories | established to perpetuate the
original location of this corner:**

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown
on the **DIAGRAM**, SET 8" in the ground and raised a mound of stone and
earth around the pipe.

From Which:

A Pine 16" dia., Bears N47°W., 40.7 ft., scribed: T11S R30E S20 BT
A Juniper 8" dia., Bears N15°E., 58.8 ft., scribed: T11S R30E S21 BT
A Pine 8" dia., Bears S32°E., 37.3 ft., scribed: T11S R30E S28 BT
A Pine 10" dia., Bears S66°W., 15.8 ft., scribed: T11S R30E S29 BT
Measurements to trees taken with a metal tape and magnetic compass,
with Declination set off 20 deg. East.
Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing
Tree Sign above blaze, and warning sign on back of each tree. Painted
a 6" red band at breast ht. around each tree. Set steel fence posts with
warning & Boundary Signs, North 9 ft. and East 1.5 ft. in the stone mound.



This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: Sept. 4, 1986
Refer to Map of Survey No. 955

Office of Surveyor County of Grant
State of Oregon hereby certify that the within instrument was filed in this office
for record on the 18 day of Dec, 1986
Robert D. Sugitt by _____
(COUNTY OFFICIAL) (DEPUTY)