

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. T-7

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T11S R30E
C 1/4
S29
1986
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 16" in the ground and raised a mound of stone & earth around the pipe.

From Which:

A Pine 12" dia., Bears N 60°29'W., 146.2 ft., scribed: C1/4 S29 BT

A Pine 16" dia., Bears N49°23'E., 164.1 ft., scribed: C1/4 S29 BT

Measurements to trees taken with an Electronic Tacheometer with angles turned from the survey control network.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence post with warning & Boundary Signs, South 5 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1969
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: Sept. 5, 1986
Refer to Map of Survey No. 955

Office of Surveyor County of Grant
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the 18 day of Dec, 1986
Robert D. Beatty by _____
(COUNTY OFFICIAL) (DEPUTY)