

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. V-19

History of original corner establishment:

Corner originally established by
Samuel W. Lackland, in 1881, under
General Land Office Contract No. 415
Surveyor Generals Notes State:
Set Basalt Stone 18x12x7 ins,
14 ins in ground for 1/4 Sec. Cor.
marked 1/4 on N face. Raised mound
of stone alongside.

DIAGRAM

T11S R30E
S26
1/4-.-
S35
1985
PLS 848

Description of corner evidence found:

No evidence is found, the area has been logged and
thinned.

No Bearing Trees are originally established.

The Corner has been lost to logging, therefore the
position is determined by proportionate measure
Between the corner found 1/2 mi. West and the
proportioned Section Corner 1/2 mi. East.

**Description of monument and accessories I established to perpetuate the
original location of this corner:**

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown
on the **DIAGRAM**, SET 20" in the ground, and raised a mound of stone & earth
around the pipe.

From Which:

A Pine 10" dia., Bears N49°W., 7.8 ft., scribed: 1/4 S26 BT

A Pine 11" dia., Bears S48°W., 16.3 ft., scribed: 1/4 S35 BT

Measurements to trees taken with a metal tape and magnetic compass,
with Declination set off 20 deg. East.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing
Tree Sign above blaze, and warning sign on back of each tree. Painted
a 6" red band at breast ht. around each tree. Set steel fence post with
warning Sign, North 4 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1985
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: Oct. 14, 1985
Refer to Map of Survey No. 904

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 20 day of Dec, 1985
Robert D. J. [Signature] by _____
(COUNTY OFFICIAL) (DEPUTY)