

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. X-16

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T11S R30E
E1/16
C--C
S34
1985
PLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 24" in the ground placed a mound of stone around the pipe. From Which.

A Fir 24" dia., Bears S11⁰E., 3.5 ft., scribed: C-E1/16 S34 BT

A Fir 10" dia., Bears N16⁰W., 34.7 ft., scribed: C-E1/16 S34 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, North & West 5 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1969
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: May 5, 1985
Refer to Map of Survey No. 904

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 20 day of June, 1985
Robert D. Gage by _____
(COUNTY OFFICIAL) (DEPUTY)