

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. A-13

History of original corner establishment:

In May, 1873, under GLO Contract No. 185, W.W. Byars set a stone 14x10x8 for cor. to Sections 3, 4, 33 and 34.

In March, 1881 under GLO Contract 383, H. Gradon found the stone 14x10x8 ins. marked with 3 notches on E. and 3 notches on W. edges. Repaired by raising mound of stones.

DIAGRAM

T11S R30E

S33 | S34

S4 | S3

T12S

Description of corner evidence found:

Found original stone 14"x12"x8", 3 inches in ground with faint 3 notches on East and West sides in mound of stone. Also found Ponderosa Pine 20" dia. with open blaze and visible "BT" scribed in it with three small "US" stamped in the blaze bearing N76°W., 56.7 ft. This tree is not on any records.

Description of monument and accessories I established to perpetuate the original location of this corner:

In place of original stone set 2 1/2"x30" aluminum pipe with 3 1/4" aluminum cap stamped:
Set pipe 10" in ground with original stone buried alongside and mound of stone to cap.

T11S R30E

S33 | S34

S4 | S3

T12S

1981

OR PLS 1294

New bearing trees:

A P. Pine 18" dia. bears N65° E., 54.4 ft. scribed T11S R30E S34 BT.

A P. Pine 18" dia. bears S26°E., 51.8 ft. scribed T12S R30E S3 BT.

A P. Pine 14" dia. bears S13°W., 42.8 ft. scribed T12S R30E S4 BT.

Attached 54-3 and 54-4 signs to all BT's and brass washer stamped LS 1294 to foot blaze of new BT's. Painted blazes and 6" band around all BT's red. Attached 54-2 and 54-4 signs to metal post 6 ft. West of corner.

Magnetic Declination= 19°30'E

I hereby certify the above corner monument was reestablished as herein described on September 18, 1981.

Witnesses: R. Orton
G. Orton

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
SEPTEMBER 23, 1977
HOWARD L. PERRY
1294

Office of..... County Surveyor..... County of..... Grant
Oregon
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 1982
..... by
(COUNTY OFFICIAL) (DEPUTY)