


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Nothing established in original survey



Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 3" Aluminum cap on 2 1/2" Aluminum pipe 30" long & buried 12" in ground with mound of stone to cap.

New Bearing Trees:

- 9" P.Pine, S33°W, 43.3', Scribed 1/4 S1, B.T.
- 12" P.Pine, S73°E, 20.9', Scribed 1/4 S1, B.T.

All B.T.'s have sign 54-4 & 54-3 attached. Set steel guard post with 54-9 & 54-2 sign, 4' South and East of monument. Painted red band around bearing trees. Tagged trees with L.S. 980 washer.


MONUMENT STAMPED:

Witnesses: David Scott, Party Chief  
Harold Pavey, Chainman

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Edgar W. Graves*

OREGON  
JULY 14, 1972  
EDGAR W. GRAVES  
980



Office of *Seminole* County of *Grant*  
 State of *Oregon*, I hereby certify that the within instrument was filed in this office  
 for record on the *2* day of *Sept*, 19*80*  
*Robert D. Bayne* by \_\_\_\_\_ (DEPUTY)  
 (COUNTY OFFICIAL)