


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. Y-7
History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.



Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.


Description of monument and accessories established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, SET 20" in the ground and placed a ring of stone filled with earth around the pipe.

From Which:

A Fir 16" dia., Bears N12°E., 12.1 ft., scribed: C-S 1/16 532 BT
A Tamarack 9" dia., Bears S 8°W., 29.2 ft., scribed: C-S 1/16 532 BT
Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, South 4 ft. & East 6 ft. from the corner.



This work is performed by:
Douglas M. Ferguson PLS 848
Mt. Vernon Oregon.
On: June 25, 1986
Refer to Map of Survey No. 941

Office of Sumner County of Grant
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the 25 day of June, 1986
Robert D. Engler by Douglas M. Ferguson
(COUNTY OFFICIAL) (DEPUTY)