


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None




Description of corner evidence found:

None


This corner is the intersection of the center of section line and the East line of HES 252

Description of monument and accessories established to perpetuate the original location of this corner:

A standard 3 1/4" diameter aluminum cap, with magnet attached to underside, mounted on a 2" diameter by 30" long aluminum pipe. The monument is surrounded by a mound of stone and is stamped as shown.



5/8" x 30" iron rods with plastic caps, one stamped "RM LS 815 51.80" bears N 87° E, 51.80 Feet and the other, stamped "RM LS 815 26.99" bears South 26.99 feet.



Office of Surveyor County of Grant
 State of Oregon I hereby certify that the within instrument was filed in this office
 for record on the 18 day of Jan, 1985
Robert D. Blaylock by _____
 (COUNTY OFFICIAL) (DEPUTY)