

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

The original corner was established in 1881 by Robb & Gradon
under Contract No. 383.

The original notes state:

589°37'W on true line on North Boundary of Sec 2
40.00 Set stone 14x14x10 for 1/4 sec cor from which
A Fir 10 in dia bears N20°E 25 lks dist.
A Fir 13 in dia bears S40°W 22 lks dist.

DIAGRAM

T11S R34E
S35
1/4---
S2
T12S

Description of corner evidence found:

Found no evidence of the original stone.

A 20" double Fir bears N20°E 16.5 ft to face (record), visible scribing.
Approximate roothole bears S40°W 15 ft (S40°W 22 lks), no above ground remains.

Description of monument and accessories I establish to perpetuate the original location of this corner:

As the position of the Sec 2 bearing tree is not firmly established,
I reestablished this corner at record distance and direction from
the Sec 35 bearing tree. Set a 2-1/2x30" aluminum monument 20" in
the ground in a mound of stone.

New BTs:


A 10" Fir bears N60°52'E 19.7 ft, scribed 1/4S35BT.
A 13" Fir bears S26°39'E 18.3 ft, scribed 1/4S2BT.

T11S R34E
S35
1/4---
S2
T12S
PLS1918
1989

Sun Cadastral Survey, 53-04H1-7-4011
Project No. 8722M
Field Book: 8-4
Work Accomplished: 8/13/89
Witnesses: Louise Parsons

New BTs have 3/4" brass washers marked PLS1918 attached to the BT
blaze, faces and bands painted with red tree marking paint, and
BT tags and Land Survey Monument signs. A steel fence post with Land
Survey Monument sign is driven approximately 3-5 feet from the corner.

PARSONS SURVEYING
1915 S.E. Stone Street
Corvallis, OR 97333
(503) 752-7515



Reference: CS 1102

Office of SURVEYOR County of GRANT
State of OREGON, I hereby certify that the within instrument was filed in this office
for record on the 21 day of Nov, 1989

Robert D. Sayers by _____
(COUNTY OFFICIAL) (DEPUTY)