

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


INDEX No. Metes and Bounds - SW Corner

History of original corner establishment:

None. Corner established this survey.

DIAGRAM

T11S R35E



1992
PLS 2405

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/4" aluminum cap, stamped as shown on the DIAGRAM, 22" in the ground and raised a mound of stone and earth around the monument. From Which:

As references set 5/8" x 30" rebars with yellow plastic caps marked PLS 2405, 28" in the ground, which bear as follows:

- N45°W, 8.6 ft.
- N45°E, 8.7 ft.

Measurements to rebars taken with a magnetic compass, declination 20° East, and a nylon clad steel tape. Set steel fence post with Land Survey Monument (54-9) sign 5' east of the monument.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Susan E. Newstetter

OREGON
JULY 26, 1989
SUSAN E. NEWSTETTER
2405

This work was performed by:
Susan E. Newstetter PLS 2405
Witnessed by: D. Mitchell Ferguson
and Rick Saul
November 3, 1992
Refer to Grant Co. Survey No.: 1239

Exp: 12/31/94

Office of Surveyor County of Grant
State of OR I hereby certify that the within instrument was
filed in this office for record on the 20 day of Jan., 1993
Robert D. Sapp by _____
(COUNTY OFFICIAL) (DEPUTY)