

RECEIVED A
FILE
 JUN 7 1971
John Liveira
 JOHN LIVEIRA, County Clerk

CORNER RESTORATION


By.....Deputy

CORNER North ¼ S9 TWP 11S RANGE 35E

ORIGINAL SURVEY BY: Robb & Gradon

CONTRACT NUMBER: 383

CONTRACT DATE: March 26, 1881



ORIGINAL DESCRIPTION:

Set basalt stone 20"x14"x 10", for ¼ sec. cor., from which a tamatack 20 in. dia. bears S 30°E, 33 lks. dist. A pine 6 in. dia. bears N 25° W, 40 lks. dist.

RESTORATION BY, STAMP AND DATE:

BAGETT, GRIFFITH & FERGUSON
 170 S. DAYTON - PH. 575-1251
 JOHN DAY, OREGON 97845

REGISTERED
OREGON
 LAND SURVEYOR

Robert D. Bagett

JULY 12, 1963
 ROBERT D. BAGETT
 598

May 23, 1971

EVIDENCE FOUND:

Found basalt stone 17"x11"x12" marked ¼ on west face. From which the original bearing trees are found as follows.
 A 30" tamarack with scribing visible in old blaze which has been opened by the U.S.F.S. bears S 30°E 23 ft. dist.
 A 18" pine with old blaze healed bears N 22°W 27 ft. dist.
 We did not reopen old blaze.
 U.S.F.S. Attention signs are on both trees and both trees are in good condition.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:


Show how trees are scribed and basis of bearings, including compass var.

Set 1½"x36" iron pipe 36" in the ground, marked as shown. Placed original stone west and alongside pipe and raised a mound of stone around pipe.

No new bearing trees are taken as both original trees are in good condition.

Used compass var. 20°

MONUMENT MARKED



Complete and File with Office of the Grant
 County Surveyor, Grant County, Oregon,
 Courthouse, Canyon City, Oregon 97820