

RECEIVED AND

FILE

JUN 7 1971

JOHN LIVEIRA, County Clerk

CORNER RESTORATION

By \_\_\_\_\_ Deputy

CORNER West 1/4 S 10 TWP 11 S RANGE 35 E

ORIGINAL SURVEY BY: Robb & Gradon

CONTRACT NUMBER: 383

CONTRACT DATE: March 26, 1881

XX		10	

ORIGINAL DESCRIPTION:

Set stone 18"x14"x12" for 1/4 sec cor.  
 from which  
 A pine 24 in. dia. bears S 40°W 43 lks. dist.  
 A pine 36 in. dia. bears N 30°E 23 lks. dist.

RESTORATION BY, STAMP AND DATE:

**BAGETT, GRIFFITH & FERGUSON**  
 170 S. DAYTON - PH. 575-1251  
 JOHN DAY, OREGON 97845

REGISTERED  
**OREGON**  
 LAND SURVEYOR

*Robert D Bagett*

JULY 12, 1963  
 ROBERT D. BAGETT  
 598

May 23, 1971

EVIDENCE FOUND:

Found 18"x14"x12" stone marked 1/4 on west face. from which the original bearing trees are found as follows.  
 A rotten, 36 in. pine stump bears N 25°E 23 lks. dist. no scribing visible.  
 A rotten 30 in. pine stump bears S 45°W 43 lks. dist. with scribing visible.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:


Show how trees are scribed and basis of bearings, including compass var.

Set 1 1/2"x36" iron pipe 14" in the ground with brass cap marked as shown. Placed original stone in ground north and alongside pipe and raised a mound of stone around pipe.

From which a white fir 8 ins. dia. bears N 79°W 12 ft. dist. marked T11S R35E 1/4 S10 BT.  
 A tamarack 8 in. dia. bears S 60°E 15.7 ft. dist. marked T11S R35E 1/4 S9 BT.

Used compass var. 20°

MONUMENT MARKED



Complete and File with Office of the Grant  
 County Surveyor, Grant County, Oregon,  
 Courthouse, Canyon City, Oregon 97820