

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by H. D. Graddon and Bamford Robb, US Deputy Surveyors, during the original survey Joint Contract No. 383 dated March, 1881.

Set basalt stone 10x10x5 for Cor to Sec's 10, 11, 14 & 15 from which

- A pine 36 ins diam bears N25°E, (23.8')36 lks dist
- A pine 28 ins diam bears S80°E, (46.2')70 lks dist
- A pine 20 ins diam bears S10°W, (44.2')67 lks dist
- A pine 40 ins diam bears N55°W, (71.3')108 lks dist

DIAGRAM

T11S R35E

S10	S11
S15	S14

1986
PLS 699

Description of corner evidence found:

Did not find any evidence of the stone the area being beside an old road and heavily logged many years ago.

- 25° Ponderosa pine (5' Stump) (Scribing Visible) (1881 BT) bears N26° 15'E, 24.8 feet.
- Stump hole (1881 BT) bears at record
- Down and rotting away stump with no visible markings (1881 BT) bears at record
- 24° Ponderosa pine (5' Stump) (Blaze with no visible scribing) (1881 BT) bears N56°W, 72.4 feet.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 3 1/4" aluminum cap, marked as shown in the diagram, 26" in the ground, at the point determined by the bearing trees. Built a mound of rock & earth to be 36" in diameter by 4" high around the monument, from which new BTs are:

- 15° Ponderosa pine bears N54° 30'W, 29.0 feet scribed T11SR35E S10 BT
- 15° Ponderosa pine bears N48° 15'E, 28.6 feet scribed T11SR35E S11 BT
- 14° Ponderosa pine bears S3° 45'E, 26.5 feet scribed T11SR35E S14 BT
- 12° Ponderosa pine bears S74° 30'W, 36.8 feet scribed T11SR35E S15 BT

Attached BT and Attention signs to and painted a red band around each BT. Bearings were taken with a staff compass, using a declination of 18° 30'E, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set a steel fence post 5 feet N of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on July 18, 1986, I monumented the corner as herein described.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Leland Lee Myers

OREGON
JULY 9, 1965
LELAND LEE MYERS
699

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 6 DAY OF April, 1987

Robert D. Bayart

Grant County Surveyor