


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

N-13

History of original corner establishment:

Corner established under joint G.L.O. contract No. 383 by Robb and Gradon dated March 26, 1881.

Set a basalt stone 12"x10"x4" and built stone mound as per instructions, For cor. to sec's. 15, 16, 21 and 22.



From which:

A pine 12 ins. dia. bears N. 40° E. 39.9 lks. dist.

A pine 18 ins. dia. bears N. 15° W. 190 lks. dist.

Description of corner evidence found:

No corner evidence found.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the apportioned corner position set a 1" x 30" pipe with a 2 1/2" brass cap 26 ins. into the ground and constructed a 36 in. dia. stone mound around it. The cap is marked as shown in the corner diagram.

Bearing objects:

Set four, 5/8" x 30" steel rebar flush to the ground with a plastic cap marked PLS 1206. The bearings and distances from the monument to the rebar are as follows:

- N. 44° W. at 25.0 ft.
- N. 46° E. at 25.0 ft.
- S. 44° E. at 25.0 ft.
- S. 46° W. at 25.0 ft.

I certify that this corner was properly remonumented under my supervision as witnessed by Tom Fisk and Andy Marlette on Sept. 15, 1989.

See Survey No. 1176 filed in Grant County Surveyors office.

REGISTERED PROFESSIONAL LAND SURVEYOR

*James D. Hanley*

OREGON  
SEPTEMBER 23, 1977  
JAMES D. HANLEY  
1206

Office of Surveyor County of Grant  
 State of Oregon, I hereby certify that the within instrument was filed in this office  
 for record on the 31 day of JULY, 1991  
Robert H. Begett by \_\_\_\_\_  
 (COUNTY OFFICIAL) (DEPUTY)