


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

P-13

History of original corner establishment:

Original corner established in 1881 by Robb & Graden.

Set stone 14x12x8 from which:
 A 12" black pine brs. West 78 lns.
 A 12" black pine brs. N78°E 23 lns.



Description of corner evidence found: 14x12x8 stone, firmly set, marked $\frac{1}{4}$ on West face.

Description of monument and accessories I established to perpetuate the original location of this corner: Set 2 1/2" x 30" aluminum pipe with 2 1/2" aluminum cap rising 2" in dirt & stone mound. Buried original stone alongside.

Witness accessories:

5/8" x 30" iron rod with 1 1/2" aluminum cap brs. S19°N 5.1' Cap marked $\frac{1}{4}$ S. 21 R.P.

5/8" x 30" iron rod with 1 1/2" aluminum cap brs. S51°E 5.7' Cap marked $\frac{1}{4}$ S. 22 R.P.

Cap marked

THIS R35E
 $\frac{1}{4}$
 521 | 522
 1989
 45 1020

I hereby certify the above corner was perpetuated as described in Aug. 1989.

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

George W. Colvin, Jr.
 OREGON
 FEBRUARY 14, 1975
 GEORGE W. COLVIN, JR.
 1020

Office of County Surveyor County of Grant
 State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 1 day of Dec, 1989
Robert D. Dwyer by _____
 (COUNTY OFFICIAL) (DEPUTY)